TOP SECRET

5-17846

COPY 19 4 PAGES TCS 8858/65

DATE June 1965

CENTRAL INTELLIGENCE AGENCY
PHOTOGRAPHIC INTELLIGENCE DIVISION
PHOTOGRAPHIC INTELLIGENCE REPORT

SHEN-YANG AIRFIELD NORTH

AND AIRFRAME PLANT 112

CIA/PIR-7008/65

graphical St. F. S.

The CIA Photo Intelligence Division has replaced the informal Inter-Office Memorandum with this new series of CIA Photographic Intelligence Reports.

Declass Review by NIMA/DOD

Handle Via TALENT - KEYHOLE Control Only

WARNING

This document contains classified information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793 and 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner to the prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive TALENT-KEYHOLE information. Its security must be maintained in accordance with KEYHOLE and TALENT regulations.

CECDET

CROUP 1

Excluded from nutromotic description and declaration and declarations are

TOP SECRET RUFF

Handle Via TALENT-KEYHOLE Control System Only

TCS 8858/65

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

SHEN-YANG AIRFIELD NORTH AND AIRFRAME PLANT 112

- 1. Shen-Yang Airfield North and Airframe Plant 112 (41 52N-123 26E) located 4 nm north of Shen-Yang as searched for aircraft, crates, and construction material.
- 2. A total of 2 FARMER and 25 probable FARMER are parked in the aircraft repair facilities area, on the alert apron and on the parking apron at the south end of the airfield. One possible partly assembled FARMER is located in front of the repair hanger (annotation 30) and consists of a fuselage with the left wing and tail section attached and the right wing lying on the ground at the right side of the aircraft. No other aircraft, aircraft parts or aircraft construction materials were observed either at the airfield or in the plant area.
- 3. Nine crates 15 feet X 5 feet are located in front of the repair hanger.
- 4. There has been no new construction at either the plant or airfield 25X1C since Mission
 - 5. All measurements have been made by the NPIC Technical Intelligence Division, have and the resultant pair image quality limit the accuracy of the measurements to whichever is greater.

ENCLOSURES:

1 Annotated photo

25X1D

Handle Via TALENT-KEYHOLE Control System Only

TOP SECRET RUFF

TCS 8858/65

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

25X1D

REFERENCES

PHOTOGRAPHY

MAPS OR CHARTS

* U.S. Air Target Chart, Series 200, Sheet 0290-11HL, 3rd Edition, December 4961 (SECRET).

REQUIREMENT

12

CIA. C-RR5-80,601

CIA/PID PROJECT

30710-5

Mandle V a
TALENT-REYMOLE
Control System Only

Approved Formelease 2000/08/312/G/ARDP78T05439A000500170005

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

KEY TO ANNOTATIONS ON THE GRAPHIC OF SHEN-YANG NORTH AIRFIELD AND AIRFRAME PLANT 112.

		* * * * * * * * * * * * * * * * * * * *	- //
1.	Wind.	tunn	e1

- 2. Gas Dynamics facility
- 3. Workshop/machine shop
- 4. Workshop/machine shop
- 5. Unidentified building
- é. Unidentified building
- 7. Workshop
- 3. Workshop/warehouse
- 9. Probable POL storage area
- 10. Transformer yard
- 11. Powerplant
- 12. Workshop/machine shop
- 13. Aircraft test revetment
- 14. Final assembly hall
- 15. Subassembly shop
- 16. Subassembly shop
- 17. Forme/foundry
- 1c. Workshop/machine shop
- 19. Warehouse
- 20. Subassembly/machine shop
- 22. Emmineering/workshop

and the state of the state of

- 23. Workshop/machine shop
- 24. Administration/engineering
- 25. Administration
- 26. Warchouse
- 27. Workshop/machine shop
- 25. Workshop
- 29. Workshop
- 30. Repair han er
- _31. Workshop
 - 32. Administration (two stories

Handle Via TALENT-KEYHOL Control System Of

